

POWER SUPPLY PREPARATION FOR USE WITH PRODUCTS WITH SCREW TERMINALS

12V or 24V Power Supply (appearance may vary)



Cut the connector off
of the supplied wallwart



Strip wire ends to
expose about 1/4" of wire

Insert wires into screw terminal
and tighten screws. Be sure to
observe polarity as noted below.



GND = Solid Black Wire

V+ = White dashed Black Wire

Dashed White Line

Note:

It is not necessary to observe polarity
when connecting to products with
an AC/DC inputs.

REV. LEVEL	REF. ECO	REV. DATE	APPROVED	DESCRIPTION
1		08/12/08		Changed to MULTIPLE products, and revised notes
2		08/05/2011		UPDATE POWER SUPPLY IMAGE

FSR

244 BERGEN BLVD.
W. PATERSON, NJ 07424
TEL. (973) 785-4347

Power Supply Preparation

PRODUCT:	MULTIPLE	PART#	28296-7
DRAWN BY:	A.B.	DATE:	08/05/2011
APPROVED BY:		DATE:	
DWG.#	C-1055A	REV.	2
		PAGE	1
		OF	1