

POWER SUPPLY PREPARATION FOR USE WITH PRODUCTS WITH SCREW TERMINALS



Cut the connector off of the supplied wallwart




GND = RIBBED Black Wire


V+ = Solid Black Wire

Strip wire ends to expose about 1/4" of wire and insert wires into screw terminal and tighten screws. Be sure to observe polarity.

Connect Power Supply to this screw terminal



After installing the under table lamp bracket, pass the power wire harness shown in picture through this hole.



Pull the wire harness and plug as shown.

FSR

244 BERGEN BLVD.
W. PATERSON, NJ 07424
TEL. (973) 785-4347

T3 WITH 3P-XLR AND DUAL USB CHARGER

PRODUCT:	CUSTOM	PART#	43055
DRAWN BY:	A.B.	DATE:	03/04/2014
APPROVED BY:		DATE:	
DWG.#	C-1168A	REV.	PAGE 1 OF 1

REV. LEVEL	REF. ECO	REV. DATE	APPROVED	DESCRIPTION