




1. DETERMINE LOCATION AND CUT  $6\text{-}1/16 \times 5\text{-}3/16$  HOLE WITH  $3/8$  MIN -  $5/8$  MAX RADIUS CORNERS IN TABLE TOP.




2. INSTALL MOUNTING BRACKETS TO ASSEMBLY AND SECURE TO TABLE BY SCREWING MOUNTING SCREWS TO UNDERSIDE OF TABLE.




## BEFORE TIGHTENING CABLE TIES, DO THE FOLLOWING:

1. Ensure loop for the A/C cord does not touch any edge when in the open position.
2. Test cycle the unit to ensure AC cord make contact with any edges or components inside the box.



**Shown with lid closed.**



**Shown with lid opened.**