




Cut the connector off of the supplied wallwart if required
Power Supply style and termination may vary



Replace connector with
2 pin Phoenix connector
using screw terminals



Note: Attention to polarity
is not important.

FSR

244 BERGEN BLVD.
W. PATERSON, NJ 07424
TEL. (973) 785-4347

Wallwart PS modification

PRODUCT:	CDA-2EQA	PART#	15868
DRAWN BY:	RLK	DATE:	7-31-03
APPROVED BY:		DATE:	
DWG.#	C-1024	REV.	0
		PAGE	1
		OF	1

REV. LEVEL	REF. ECO	REV. DATE	APPROVED	DESCRIPTION