


POWER SUPPLY PREPARATION

12VDC Power Supply (appearance may vary)



Cut the connector off of the supplied wallwart

Strip wire ends to expose about 1/4" of wire



WHITE STRIPED WIRE IS THE POSITIVE LINE (+12VDC)

FSR

244 BERGEN BLVD.
W. PATERSON, NJ 07424
TEL. (973) 785-4347

Power Supply Preparation

PRODUCT: CUSTOM T3 WITH 2 USB-SNAP-IN CHARGERS	PART# 99561
DRAWN BY: A.B.	DATE: 08/06/2014
APPROVED BY:	DATE:
DWG.# C-1171	REV. - PAGE 1 OF 1

REV. LEVEL	REF. ECO	REV. DATE	APPROVED	DESCRIPTION